/			
ATY LOCATED AT: _	1317 Hindely	Rd.	Clinton

#### PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

	SECTION I — WATER SUPPLY				
TYPE OF SYSTI	EM: Public Private Seasonal Unknown Drilled Dug Other				
MALFUNCTION	NS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?				
	Pump (if any):				
	Quantity: Yes V No Unknown				
	Quality: Yes V No Unknown				
	If Yes to any question, please explain in the comment section below or with attachment.				
WATER TEST:	Have you had the water tested?				
	To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?				
	If Yes, are test results available?				
	What steps were taken to remedy the problem?				
ID DDILLAGE (C)					
•	trike Section if Not Applicable):				
INSTALLAT	ION: Location: Front Lawn under well House				
•	Installed by:				
USE:	Number of persons currently using system:				
OSE.	Does system supply water for more than one household? Yes W No Unknown				
Comments: 1/2	boes system supply water for more than one nousehold: Tes is two is challown.				
710					
Source of Section	ı I information:				
Buyer Initials	Page I of 7 Seller Initials Mn				
Aimì Baldwín	Phone: (207)266-7021 Fax: Produced with Lone Wolf Transactions {zipForm Edition} 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com				

Y LOCATED AT:
SECTION II — WASTE WATER DISPOSAL
TYPE OF SYSTEM: Public Private Quasi-Public Unknown
IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable): Have you had the sewer line inspected?
If Yes, what results:  Have you experienced any problems such as line or other malfunctions?
IF PRIVATE (Strike Section if Not Applicable):  Tank: Septic Tank Holding Tank Cesspool Other:  Tank Size: 500 Gallon 1000 Gallon Unknown Other:  Tank Type: Concrete Metal Unknown Other:  Location: Beliech House OR Unknown  Date installed: 2660 Date last pumped: 2020 Name of pumping company: Cm5'  Have you experienced any malfunctions? Yes Note of Pumping Company: Yes Note of Pumping Compan
Date of last servicing of tank: 2020 Name of company servicing tank: 2MS  Leach Field: Yes No Unknown  If Yes, Location: Brhind Hose  Date of installation of leach field: 2000 Installed by: Unknown  Date of last servicing of leach field: Ma Company servicing leach field:  Have you experienced any malfunctions? Yes No  If Yes, give the date and describe the problem and what steps were taken to remedy:
Do you have records of the design indicating the # of bedrooms the system was designed for?  Yes No  If Yes, are they available? Yes No  Is System located in a Shoreland Zone? Yes No  Comments:
Source of Section II information:
Buyer Initials Page 2 of 7 Seller Initials <u>Μη</u>
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com .

1 1 to 1 to 1

PRO	PERT	ΥI	LQÇA'	TED	AT

SECTION III — HEATING SYSTEM(S)/HEATING SOURCES(S)				
Heating System(s) or Source(s)	SYSTEM !	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	+ Ha	STSTEME	3131EW13	5151EM 4
Age of system(s) or source(s)	2005	,		
Name of company that services				
system(s) or source(s)	tim Hoseia			
Date of most recent service call	oet 2021			
Annual consumption per system or source (i.e., gallons, kilowatt				
hours, cords)	275 Jal			
Malfunction per system(s) or	7 0 - 1			
source(s) within past 2 years				
Other pertinent information				
Are there fuel supply line	s?		Yes	No Unknown
Are any buried?	•			No Unknown
Are all sleeved?			<u></u> , <u>'</u>	No Unknown
Chimney(s):			<del></del>	_  No
If Yes, are they lined:		***************************************	Yes	No Unknown
Is more than one heat	source vented through	one flue?	Yes	No Unknown
Had a chimney fire: .	********************************		Yes	No Unknown
	inspected?			No Unknown
If Yes, date:	peerea	******************************		140 [2] CIIKIIOWII
	1			
	eleaned: <u>Vn Kno ~</u>			_
Direct/Power Vent(s):	***************************************	• • • • • • • • • • • • • • • • • • • •	Yes	∠No Unknown
Has vent(s) been inspe	ected?	*****************************	Yes	No Unknown
If Yes, date:			<del></del> ,	
Source of Section III infor	rmation:			
		MAZADDOHG M	- CREIN - I	
		– HAZARDOUS M	<u> </u>	
The licensee is disclosing		<b>*</b> •		
A. UNDERGROUND	STORAGE TANKS	- Are there now, o	r have there ever be	en, any underground
storage tanks on the prope	erty?	********************************	Yes	No Unknown
If Yes, are tanks in curren	t use?	*******************************	Yes	No Unknown
If no longer in use, how lo				
			DEP? Yes	No Unknown
If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown Are tanks registered with DEP? Yes No Unknown				
Age of tank(s):				
Locations				·
Buyer Initials		Page 3 of 7	Seller Initials M1	
Produced with	Lone Wolf Transactions (zipForm Editio	n) 717 N Harwood St, Suite 2200, Da	ilas, TX 75201 www.lwolf.com	

PROPERTY LOCATED AT:		
What materials are, or were, stored in the tank(s)?		
Have you experienced any problems such as leakage:	\ \ Yes	No Unknown
Comments: no under ground stores tant		
Source of information: Seller		<del></del>
B. ASBESTOS — Is there now or has there been asbestos:		
As insulation on the heating system pipes or duct work?	Yes	W No ☐ Unknown
In the ceilings?		No Unknown
In the siding?		No Unknown
In the roofing shingles?		No Unknown
In flooring tiles?		No Unknown
Other:n c		
Comments: No Know Esbestos	168	∐ No ∐ Unknown
C. RADON/AIR - Current or previously existing:		
Has the property been tested?	□ Voc	No Unknown
If Yes: Date:By:		
Results:		
If applicable, what remedial steps were taken?		
Has the property been tested since remedial steps?		No Unknown
Are test results available?	<del></del>	No No
Results/Comments: no Known Radonlair		
Source of information:		
D. RADON/WATER - Current or previously existing:		-::
Has the property been tested?		No Unknown
If Yes: Date:By:	<del></del>	
Results:		
If applicable, what remedial steps were taken?		
Has the property been tested since remedial steps?		No Unknown
Are test results available?		□ No
Results/Comments: No Known Radon lar		
Source of information: Seller		
E. METHAMPHETAMINE - Current or previously existing:	Yes	No Unknown
Comments: no Known methan phetan.		
Source of information: Setter		
Buyer Initials Page 4 of 7 Selle	r Initials <u>MN</u>	
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX	75201 <u>www.fw.olf.com</u>	

PROPERTY LOCATED AT:	
F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in hor constructed prior to 1978)	nes
Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?	
Yes No Unknown Unknown (but possible due to a	ge)
If Yes, describe location and basis for determination:	<b>D</b> -7
Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes	— Io
If Yes, describe:	
Are you aware of any cracking, peeling or flaking paint?	— Io
Comments: No trown read based paint / Hezard	
Source of information: Selle 6	_
G. OTHER HAZARDOUS MATERIALS - Current or previously existing:	_
TOXIC MATERIAL: Yes V No Unknown	vn
LAND FILL: Yes V No Unknow	
RADIOACTIVE MATERIAL: Yes V No Unknown	
Other: No Known Hazardows materials	
Source of information: Setter	
Buyers are encouraged to seek information from professionals regarding any specific issue or concern.	_
SECTION V — GENERAL INFORMATION	
Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights first refusal, life estates, private ways, trails, homeowner associations (including condominiu and PUD's) or restrictive covenants?	ms
Is access by means of a way owned and maintained by the State, a county, or a municipal	-
over which the public has a right to pass? Yes Unknow	n
If No, who is responsible for maintenance?	
Road Association Name (if known):	_
Buyer Initials Page 5 of 7 Seller Initials Mn	
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dalles, TX 75201 www.lwolf.com	

 $https://me.flexmls.com/cgi-bin/mainmenu.cgi?cmd=url+reports/documents/viewchecked.html \&pv=false \& list\_tech\_id=x\%27202405061821160288660...$ 

PROPERTY LOCATED AT:
Are there any tax exemptions or reductions for this property for any reason including but not limited to:
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?
Ves No I Inknow
If Yes, explain: Ho mestral Exemtion
Is a Forest Management and Harvest Plan available? Yes VNo Unknow
Is house now covered by flood insurance policy (not a determination of flood zone) Yes Vo Unknow
Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dis
water filtration system, photovoltaics, wind turbines): Type:
Year Principal Structure Built: 7005
What year did Seller acquire property? Zo21
Roof: Year Shingles/Other Installed: 200 S
Water, moisture or leakage: _ho
Comments:nonc_
Foundation/Basement:
Is there a Sump Pump?
Water, moisture or leakage since you owned the property: Yes No Unknow
Prior water, moisture or leakage? Yes No Unknow
Comments: 5lab
Mold: Has the property ever been tested for mold?
If Yes, are test results available? Yes No
Comments: None
Electrical: Fuses Circuit Breaker Other: Unknow
Comments:
Has all or a portion of the property been surveyed?
If Yes, is the survey available?
Manufactured Housing – Is the residence a:
Mobile Home
Modular
Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
Comments:
KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that me
have an adverse impact on health/safety:
Comments: None
Source of Section V information: 5ct Fer
Buyer Initials Page 6 of 7 Seller Initials MM
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

\$ 18 V B

PROPERTY LOCATED AT:			
	SECTION VI - ADDIT	IONAL INFORMATIO	ON
Both Sheds	new water	- It cater in	202/
	ECTION IN DISCLOSUR	E:	Yes V No
Seller shall be responsible a defects to the Buyer.	nd liable for any failure to	provide known informa	ation regarding known material
Neither Seller nor any Broker of any sort, whether state, mu- electrical or plumbing.	makes any representations nicipal, federal or any other	as to the applicability of er, including but not limi	f, or compliance with, any codes ited to fire, life safety, building,
As Sellers, we have provided our knowledge, all systems a	the above information and equipment, unless other	d represent that all informations and this form,	nation is correct. To the best of are in operational condition.
SELLER	DATE	SELLER	DATE
SELLER	DATE	SELLER	DATE
I/We have read and received brochure, and understand that or concerns.	l a copy of this disclosure t I/we should seek informa	e, the arsenic in wood t tion from qualified profe	fact sheet, the arsenic in water essionals if I/we have questions
BUYER	DATE	BUYER	DATE
BUYER	DATE	BUYER	DATE
F-T-9	Page ?		•
Maine Association of RE All Rights Reserved. Revis	ALTORS®/Copyright © 2022. sed 2022.		SUIAL MUSING GOUSTICATY

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

OPR BK 14307 Page 141 INSTR#: 2022000008

 BK14307
 PGS 141 - 142
 01/03/2022 10:38:21 AM

 INSTR#: 2022000008
 ATTEST: DIANE WILSON

 RECEIVED KENNEBEC SS eRecorded Document
 ACTING REGISTER OF DEEDS

Return to:

MAINE REAL ESTATE TRANSFER TAX PAID

#### WARRANTY DEED

DLN: 1002140178344

KNOW ALL PERSONS BY THESE PRESENTS: That Betsy J. Luce, of 1317 Hinckley Road, Clinton, ME 04927, for consideration paid grants to Michael Nash, of 125 Grant Street, Bangor, ME 04401, with WARRANTY COVENANTS:

#### See attached Exhibit A

Meaning and intending to describe and convey the same premises conveyed to Betsy J. Luce by virtue of a deed from Jutta Dionne dated May 7, 2008 and recorded in Book 9723, page 245 of the Kennebec County Registry of Deeds.

Executed this 30th day of December, 2021.

Betsy J. Luce

State of <u>Maine</u> County of <u>fenobscot</u>

December 32, 2021

Then personally appeared before me on this  $20^{4/4}$  day of December, 2021, the said Betsy J. Luce and acknowledged the foregoing to be her voluntary act and deed.

Notary Public/Attorney-at-Law Commission expiration:

Jacob Leonard Notary Public, Maine My Commission Expires 12/3/2027

RE: 2021-2523 Page 1 of 2

OPR BK 14307 Page 142 INSTR#: 2022000008

#### Exhibit A

A certain lot or parcel of land situated in Clinton, County of Kennebec and State of Maine, being more particularly bounded and described as follows, to wit:


Being Lot #2 on the Final Plan of Snowman Subdivision dated July 9, 1991 and recorded in the Kennebec County Registry of Deeds on July 15, 1991, as File No. D-91119, to which plan and the record thereof reference may be made for a more particular description.


The premises are conveyed subject to any easements of record and this deed includes all rights, easements, privileges and appurtenances belonging to the premises hereinabove described.

Also included are all rights to a 2005 Titan Mobile Home, Model 093 Brentwood, Serial No. 19-05093-11436.

RE: 2021-2523 Page 2 of 2

flexmls Web 5/7/24, 11:40 AM





## Arsenic in Well Water: The Problem You Can't See, Smell, or Taste

It's hard to believe that water that looks, smells, and tastes fine may not be safe to drink. But the truth is that many private wells in Maine yield water that is high in arsenic.



Arsenic is a naturally occurring chemical found in soil and rocks. Some rocks have higher levels of arsenic, and this may explain why some drilled wells have high arsenic water. And in some areas, past use of arsenic-containing pesticides on blueberry, apple and potato crops may add to the arsenic water problem.

#### The Harm Caused by Arsenic

People who drink water high in arsenic for many years are more likely to get cancer. Drinking water very high in arsenic can also cause stomach pain, nausea, vomiting and diarrhea, numbness or tingling in the hands and feet, as well as effects on blood and the heart.

1

How likely you are to get cancer or any other health effects from arsenic in water depends on three major factors:

- How much arsenic is in your water;
- How much tap water you drink;
- How long you have been drinking the water.

If you are concerned about health problems possibly due to arsenic in your well water, you should discuss them with your doctor. The Bureau of Health recommends that all household wells be tested for arsenic.



Answers to Some Commonly
Asked Questions

### Q. How much is too much arsenic in well water?

Answer: Test results for arsenic in water are often reported as the number of milligrams of arsenic in a liter of water (mg/L for short). A liter is about a quart. The Bureau of Health guideline for arsenic in domestic well water is 0.01 milligrams of arsenic per liter of water. The current federal government standard for regulated water supplies is 0.05 mg/L, but this will be lowered to 0.01 mg/L.

## Q. I just found out I have high arsenic water. What should I do?

Answer: If your water has more than 0.01 mg/L arsenic, we recommend you begin taking steps to reduce how much of this water you drink. Switching to bottled water will greatly reduce how much arsenic gets into your body. It will also allow you to safely take your time in deciding what, if any, treatment you want to have installed to remove arsenic from your well water. Sometimes, simply switching to bottled water is all that is needed.



Q. Is there a way to remove arsenic from well water?

Answer: Yes. We advise consulting one or more water treatment companies to help in choosing an arsenic removal system. This is because the choice of a treatment system depends on what else is in your water and how much water you need to treat. While we do not recommend any specific treatment system, we do advise selection of treatment systems that have been certified for arsenic removal by NSF International (www.nsf.org). Also, be sure to test at least once a year after any system is installed to make sure it is working.

2 3

## Q. Can I use my water for bathing if it has high arsenic?

Answer: Studies have shown that little arsenic gets into adults from bathing. But we do not have studies on young kids. Kids might get more arsenic in them while bathing because of their bathing habits. We have a study underway to check this. For now, if you are concerned, call us toll-free to discuss exposure

## Q. Can I use my water for cooking if it has arsenic in it?

from bathing.

Answer: The answer depends on how much arsenic is in your water, how much water is either absorbed or used when cooking a food, and how often you eat such foods. Pasta, rice, oatmeal and dried beans are examples of foods that absorb a lot of water when cooked. Soup and jello are examples of foods that use water by recipe. If your water has more than 0.05 mg/L arsenic, contact us for information about use in cooking.

## Q. How likely is it that my well water has high arsenic?

Answer: Based on the current information we have, it looks like about 1 out of every 10 Maine homes with a private well have arsenic levels of concern. Drilled bedrock wells are more likely to have high arsenic levels than dug wells, wellpoints, or wells that are drilled into sand and gravel.

4

# How do I get more information about arsenic in private well water?

► For more information on the health effects of arsenic, contact:

Andrew E. Smith, SM, ScD.
State Toxicologist
Environmental Toxicology Program
Bureau of Health
11 State House Station
Augusta, ME 04333
Toll Free: 866-292-3474
Email: andy.e.smith@state.me.us

Website:

janus.state.me.us/dhs/bohetp/index.html

 For more information on treatment systems for removing arsenic from well water, contact:

> David Braley, Geologist Drinking Water Program Bureau of Health 11 State House Station Augusta, ME 04333 Tel: (297) 287-3194

Email: david.braley@state.me.us


Website:

janus.state.me.us/dhs/eng/water/index.htm



Kevin W. Concannon, Comissioner May 13, 2002

## HAVE YOU TESTED YOUR WELL WATER FOR ARSENIC?



**Arsenic in Well Water** 



Maine Bureau of Health



## Fact Sheet: Arsenic Treated Wood

Maine CDC Environmental and Occupational Health Program

Department of Health and Human Services 11 State House Station Augusta. ME 04333 Toll Free in Maine: 866-292-3474 Fax: 207-287-3981 TTY: 207-287-8066 Email: ehu@ maine.gov

#### IF YOU WORK WITH CCA WOOD

- NEVER burn CCA wood.
- Wear gloves when handling CCA wood
- Wear a dust mask when sanding or cutting CCA wood
- Don't work with CCA wood in an enclosed area (like a garage)

Apply a coating to seal the wood every 1-2 years

#### TO LEARN MORE

Eric Frohmberg
Environmental and
Occupational Health
Program
Maine CDC
Toll-free in Maine 866292-3474
TTY: 207-287-8066
www.maine.gov/dhhs/
eohp

#### DoesYour New Home Have Arsenic (CCA) Treated Wood?

About half of all Maine homes have a deck, or playground or some other structure that is made of wood treated with arsenic. This wood is called "CCA pressure-treated wood" or just "pressure-treated" wood. The wood was treated with arsenic to protect against rot and insects.

Too much arsenic can cause cancer. So it is good to prevent arsenic getting into your body when you can. When you touch wood treated with arsenic, you can get arsenic on your hands. The arsenic on your hands can get into your mouth if you are not careful about washing before eating. Young children are most at risk because they are more likely to put their hands in their mouths. The good news is that there are simple things you can do to protect yourself and your family from arsenic treated wood. This fact sheet will tell you how.



Children touching unsealed treated wood, and then putting their hands in their mouths is the bioxest concern.

First: Does your house have arsenic treated (CCA) wood?

When arsenic treated wood is new, it tends to have a greenish tint. When CCA wood is older, it is harder to tell. Ask your realtor if the seller knows whether CCA wood was used. You can also test the wood to find out if it contains arsenic. Call us to find out how.

Second: If so, reduce contact with the arsenic.

You can lower the amount of arsenic on the surface of the wood by applying a coating on the wood every 1-2 years. Oil-based sealants, varnishes, or polyurethane work best for sealing arsenic in the wood. Be sure to wash your children's hands when they finish playing on or near CCA wood.

Third: If you have any questions, call us toll-free in Maine: 866-292-3474

### Common Questions

What is CCA wood?

CCA wood is made by dipping the wood in a mixture of chemicals. These chemicals include chromium, copper, and arsenic. This protects the wood against insects and rot. This wood is known as CCA wood or "pressure treated" wood. Most pressure treated wood in the U.S. is CCA wood. After December 31, 2003, no more CCA wood will be made for use around homes. CCA wood may still be sold for home use until April 1, 2004 in the state of Maine.

What is Arsenic?

Arsenic is found in soil and rocks. Most people get a little arsenic every day from the food they eat. Also, some people have arsenic in their private wells, which is why it is important that anyone with a well have it tested for arsenic. People who are exposed to too much arsenic over many years are more likely to get cancer.